

| Issue Date: January 25, 2023 Implementation Date: January 25, 2023 Document Type:  ☐ Bulletin ☐ Decision Status:   |   |
|--|---|
| □ Published  |   |
| ☐ Internal   |   |
| Number: SC02-2023 Event: BRMC  |   |
| Subject: Technical Regulation  |   |
| This amendment is issued under the provisions of the B confirmation that the following amendments, notice authorized to the text of the Supplementary Regularecommended that in addition to retaining a copy of this regulations according to the following: | es or points of clarification have been ation of the above named event. It is |
| Key: Deleted text: <del>crossed out text</del> New Text: <u>Highlighted and underlined</u>   |   |
| Art.3 Engine Sealing, Scrutinizing. Page No.6  |   |
| The Engine Identity Card(s), showing the matching engine serial no. (s (BIC or BIKC) signature(s) of ROTAX Authorised Distributor (BIKC) or Service Center specified in the Supplementary Regulations or Bulletin  | ROTAX MAX Challenge World Finals or the ROTAX                                 |
| Reason for change:   |   |
| As Requested by BIKC   |   |
| On Behalf of the BMF Sporting Commission   |   |

**Bahrain Motor Federation**